

REPORT OF CHANNEL CONDITIONS 400 FEET WIDE OR GREATER <i>(ER 1130-2-306)</i>					PAGE 1 OF 1			
					DATE 17 July 2002			
TO: The Record				FROM: U.S. Army Corps of Engineers 26 Federal Plaza New York, NY 10278-0090				
RIVER/HARBOR NAME AND STATE: New York Harbor, Sandy Hook Channel New Jersey					MINIMUM DEPTHS IN EACH ¼ WIDTH OF CHANNEL ENTERING FROM SEAWARD			
SECTION OR REACH	MAP FILE NO. SURVEY DATE	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	LEFT INSIDE QUARTER <i>(feet)</i>	RIGHT INSIDE QUARTER <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(nmiles)</i>	DEPTH <i>(feet)</i>				
<u>Bayside Channel</u>	File# 142 May, June & July 2002	800	3.7	35	24.9	39.5	36.9	32.9
<u>East Section</u>	File# 142 May, June & July 2002	800	3.4	35	38.9	41.1	38.0	31.8
REMARKS: 1. Some small shoals occur along the edges of the channel.								